

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1192
East
> 1
1.565 mi.
8263 ft.

SAUNDERS RESIDENCE
190 DOVER ST
BROOKLYN, NY

NY Spills S111737981
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: SAUNDERS RESIDENCE
Address: 190 DOVER ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1113250 / 2012-02-22
Facility ID: 1113250
Facility Type: ER
DER Facility ID: 415682
Site ID: 461230
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 2012-02-22
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 2012-02-22

CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-02-22
Spill Record Last Update: 2012-02-22
Spiller Name: BOB CASTORO
Spiller Company: BOBCO INC
Spiller Address: Not reported
Spiller Company: 999
Contact Name: BOB CASTORO
DEC Memo: "02/23/12-Vought-Duty desk officer. Vought called Bob Castoro (Cell:917-578-2839) and left message to return call. Received call from Castoro and customer ordered 500-gallons of #2 fuel oil and broken petrometer and spill out of vent pipe and no spill out manway of tank. No sewers or drains affected and spill on concrete using speedy dry. Petrometer will be sent out for repair and no spill inside building. Tank is a 1080-gallon #2 fuel oil AST. Spill closed by Vought."

Remarks: "on concrete - cleanup crew enroute"

All Materials:

Site ID: 461230
Operable Unit ID: 1211322
Operable Unit: 01
Material ID: 2209054
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: Not reported
Oxygenate: Not reported